

Ceramic (Body) Preparation



Raw material milling & mixing



Raw material milling & mixing



Forming



Hydraulic Pressing



Slip Casting



Extrusion Pressing



Firing



Shuttle Kilns Firing upto 1650°C



Unloading & Sorting



Finished Product